

Chart Correction

28/2005 **Ma Wan and Approaches – Kellett Bank and Sham Shui Kok – Mooring Buoys**

Source – Hong Kong Marine Department Notice No. 108 of 2005

Chart HK0802 NE September 2004

Delete  22° 17.575' N 114° 07.589' E

Chart HK0803 (Last Small Correction – 25/2005)

Insert  22° 18.246' N 114° 07.100' E

Delete  22° 17.575' N 114° 07.589' E

Chart HK1502 (Last Small Correction – 27/2005)


Insert  22° 18.246' N 114° 07.100' E

 22° 19.441' N 113° 59.504' E

 22° 19.329' N 113° 59.106' E

Chart HK3002 (Last Small Correction – 26/2005)

Insert  22° 18.246' N 114° 07.100' E

Delete  22° 17.575' N 114° 07.589' E

28/2005

馬灣及臨近水域 - 奇力灘及深水角 - 繫泊浮泡

出處 -

香港海事處報告 2005 年第 108 號

海圖 HK0802

新版 2004 年 9 月

刪去



22° 17.575' N 114° 07.589' E

海圖 HK0803

(上次小改正 - 25/2005)

加繪



22° 18.246' N 114° 07.100' E

刪去



22° 17.575' N 114° 07.589' E

海圖 HK1502

(上次小改正 - 27/2005)

加繪



22° 18.246' N 114° 07.100' E



22° 19.441' N 113° 59.504' E



22° 19.329' N 113° 59.106' E

海圖 HK3002

(上次小改正 - 26/2005)

加繪



22° 18.246' N 114° 07.100' E

刪去



22° 17.575' N 114° 07.589' E