

16(T)/2009

Lamma Channels – Western Fairway – Temporary establishment of an isolated danger buoy

Source: HK Hydrographic Office [W/F No. 13 in MDPAS/HO 6-20-2(4)] refers.

Description:


An isolated danger buoy  has been temporarily laid in position 22° 16.778'N 114° 06.340'E.

Chart Affected: HK0803, HK1501, HK1502

16(T)/2009

博寮海峽 – 西航道 – 臨時設置孤立危險浮標

出處 – 參考香港海道測量部 [W/F No. 13 in MDPAS/HO 6-20-2 (4)]。

內容 – 在 $22^{\circ}16.778' N$ $114^{\circ}06.340' E$ 處臨時設置一孤立危險浮標



有關海圖: HK0803, HK1501, HK1502