

24/2009 **South Western Approaches – Lantau Island No. 2 Anchorage – Fairway, wreck, obstruction, depths.**

Source – HK Hydrographic Office [W/F No. 19 in MDPAS/HO 6-20-2(4)]

Chart HK3002 (Last Small Correction – 21/2009)

Insert the accompanying block, showing change of 22° 18.293' N 113° 50.061' E
fairway, wreck, obstruction and depths,
centred on:

24/2009 西南臨近水域 - 大嶼山 2 號錨地 - 航道, 沉船, 障礙物, 水深

出處 - 香港海道測量部 [W/F No. 19 in MDPAS/HO 6-20-2 (4)]

海圖 HK3002 (上次小改正 - 21/2009)

加貼 隨附貼圖, 中心點為: $22^{\circ} 18.293' N$ $113^{\circ} 50.061' E$
顯示已改變的航道, 沉船, 障礙物及水深

