



9/2005 **Deep Bay – Chiwan – Leading lights**

Source – China MSA Notice No. 53&54/2005

Chart HK1504 (Last Small Correction – 8/2005)

Insert	 ★ Iso.R.4s39m5M	22° 28.767' N	113° 52.840' E
Delete	 ★ Iso.R.2s31m7M	22° 28.715' N	113° 52.847' E
Amend	light to, Oc.R.5s48m5M	22° 28.963' N	113° 52.825' E
Amend	legend to, 355° 25', centred on	22° 26.908' N	113° 53.015' E

9/2005

后海灣 - 赤灣 - 導燈


出處 -

中國海事局改正通告第 53 及 54/2005 號

海圖 HK1504


(上次小改正 - 8/2005)

加繪

☆ Iso.R.4s39m5M


22° 28.767' N 113° 52.840' E

刪去

☆ Iso.R.2s31m7M


22° 28.715' N 113° 52.847' E

更改

燈質為 Oc.R.5s48m5M

22° 28.963' N 113° 52.825' E

更改

註記為 355° 25', 中心點為

22° 26.908' N 113° 53.015' E