

**4(T)/2008**

**Urmston Road – Temporary re-positioning of lighted buoy.**

Source:

Hong Kong Marine Department Notice No. 22 of 2008 refers.

With effect from 1 February 2008 until 30 April 2008, the lighted buoy “AIRPORT 2” has been temporarily re-positioned to the following position (WGS84 DATUM) : 22° 19.805'N 113° 56.913' E.

Chart Affected:

HK1503

**4(T)/2008**

**龍鼓水道 - 臨時重置燈浮標。**

參考香港海事處佈告 2008 年第 22 號。

由 2008 年 2 月 1 日起至 2008 年 4 月 30 日，“機場 2” 燈浮標臨時重置於以下位置(WGS84 基準):  $22^{\circ} 19.805' N$   $113^{\circ} 56.913' E$ 。

**有關海圖:**

**HK1503**