


Source: Hong Kong Marine Department Notice No. 110 of 2010 refers.
Marine works are being carried out in the hatched area.

Chart Affected: HK0801, HK2501



出處 - 參考香港海事處佈告 2010 年第 110 號。
附圖陰影線標示施工範圍。

有關海圖: HK0801, HK2501

