


30(T)/2010

Urmston Road – Tuen Mun River Trade Terminal – Submarine Outfall Inspection and Cleaning Works.

Source: Hong Kong Marine Department Notice No. 98 of 2010 refers.
Submarine outfall inspection and cleaning works are being carried out in the hatched areas.

Chart Affected: HK1503



30(T)/2010

龍鼓水道 - 屯門內河碼頭 - 海底渠口檢查及清理工程

出處 - 參考香港海事處佈告 2010 年第 98 號.

附圖陰影線標示施工範圍.

有關海圖: HK1503

